

Date	Number	Name	Size	Manner of Jeweling, Balance, &c.	
Dec/72 Jan/73	666001 to 6660000	Come W.C. C.P.	18	Plain	Steel Bal
Jan. to Mar. /73	666001 " 100	P.S.B.	"	4 holes Pat. Pat.	Ex " May & Ge
Jan. & Feb. "	" 101 " 200	"	"	" "	Steel " Jan 12
" to Mar. "	" 201 " 667000	"	"	" "	Ex " Get
Mar. 1/73 } 667001 " 400	W.C.	"	"	" "	Steel " Feb 11
Dec/72 Jan/73	" 401 " 600	"	"	" "	Ex " " 8
" "	" 501 " 600	"	"	" "	Steel " March
" "	" 601 " 740	"	"	" "	Ex " "
" "	" 741 " 800	"	"	" "	Steel " March
" Jan & Feb/73	" 801 " 668000	"	"	" "	Ex " Dec 12
Jan to Mar 1873	668001 " 669400	P.S.B.	"	" "	" " "
Feb "	669401 " 500	"	"	" "	Steel " Oct.
Feb & Mar "	" 501 " 670000	"	"	" "	Ex " July 14
Jan/73 to Oct/77	670001 " 100	A.W.C. 3/4 P.	16	5 pairs Nickel Pat. Pat. S.W.C. adj.	Oct
Oct/72 to Sept/74	" 101 " 671000	Am A.W.C. "	"	4 pairs	Mar. 1.
" " May 73	671001 " 673000	Cres St. 3/4 P.	18	" "	Oct
Oct. Mar/Apr. /73	673001 " 674000	P.S.B.	"	4 holes	" " "
Dec/72 to Feb/73	674001 " 675000	Come W.C. "	"	Plain	May 12
Feb to May 1873	675001 " 676000	"	"	4 holes	" "
Jan "	676001 " 200	W.C. "	"	" Pat. Pat.	June 12
" "	" 201 " 300	"	"	" "	Brass "
" "	" 301 " 400	"	"	" "	March "
" "	" 401 " 500	"	"	" "	Ex "
" "	" 501 " 700	"	"	" "	Steel "
" "	" 701 " 850	"	"	" "	Brass "
" "	" 851 " 940	"	"	" "	Steel "
" "	" 941 " 677000	"	"	" "	Ex "
Mar/Apr/May "	677001 " 680000	P.S.B.	"	" "	June 12
Jan to Mar "	680001 " 681000	Come W.C. "	"	Plain	Steel "
Mar. May "	681001 " 682000	"	"	4 holes	" "
Apr. June "	682001 " 684900	P.S.B.	"	" Pat. Pat. Ex "	12