

No.	Date	Number	Name	Size	Manner of Jeweling	Balance, etc.
1	May & June 1877	972361 to 972390	P. S. B. Ladies	10	4 pair	Exp Bal
"	June "	" 391 " 400	A. S. & Co	"	"	" "
"	June & July "	" 401 " 480	P. S. B.	"	"	" "
"	" " " "	" 451 " 500	A. S. & Co	"	"	" "
"	" to Oct "	" 501 " 800	W. C.	"	2 pairs	" "
"	Apr. & June "	" 801 " 880	Am. W. Co. J. P.	14	"	" "
"	" & " "	" 881 " 900	" "	"	" Nameless	" "
"	" " May "	" 901 " 973000	Home Mass	"	Plain	Steel "
"	Mar. & Apr. "	973001 " 080	Am. W. Co.	"	"	Exp "
"	" " " "	" 081 " 100	" "	"	" Nameless	" "
"	" " " "	" 101 " 190	" "	"	"	Gold "
"	" " " "	" 191 " 200	" "	"	" Nameless	" "
"	Mar. to July "	" 201 " 380	" "	"	"	" "
"	Apr. & May "	" 381 " 400	" "	"	" Nameless	" "
"	" & June "	" 401 " 480	" "	"	"	" "
"	" " May "	" 481 " 500	" "	"	" Nameless	" "
"	" " " "	" 501 " 570	" "	"	"	" "
"	" " " "	" 571 " 600	" "	"	" Nameless	" "
"	May & June "	" 601 " 670	" "	"	"	Steel "
"	" " " "	" 671 " 700	" "	"	" Nameless	" "
"	" to Sept. "	" 701 " 770	" "	"	"	" "
"	Apr. to June "	" 771 " 800	" "	"	" Nameless	" "
"	" & May "	" 801 " 870	" "	"	"	Gold "
"	April "	" 871 " 900	" "	"	" Nameless	" "
"	May & June "	" 901 " 980	" "	"	"	Exp "
"	June & July "	" 981 " 974000	" "	"	" Nameless	" "
"	Mar. Apr. & May "	974001 " 975000	Broadway	18	"	nickel "
"	Apr. to June "	975001 " 500	W. C.	"	"	Exp "
"	Mar. & Apr. "	" 501 " 570	Home Mass	"	"	Steel "
"	" " " "	" 571 " 600	" "	"	" Nameless	" "
"	" " " "	" 601 " 670	" Mass	"	"	" "